Tom Buchanan
Lehrer.

Department of Natural Resources
INTRA-DEPARTMENT
MEMORANDUM

Green Bay
Station

July 23, 1975 — 4400

Date

TO: Chuck Leveque - Madison

FROM: Gary F. Kulibert

SUBJECT: The Lehrer Landfill Site

An order no. 2A-74-833 had been issued to Mr. Lehrer concerning his landfill site. As indicated in early correspondence, he did not comply with the order and was referred to the Attorney General's office. On July 14, 1975, I inspected the Lehrer landfill site to see what additional work had been done. It was noted that no waste is being disposed within 300 feet of Kankapot Creek. However, these areas have not been properly abandoned in accordance with NR 151. It appears that there is two feet of cover material placed over it, however it is not properly sloped, topsoiled or seeded. Newly arrived waste at the landfill site is not being compacted and covered on a daily basis. In some areas it appears that waste has not been covered for a considerable period of time. The worst area in the southeast end of the landfill site by the old incinerator remains uncovered. Here is where a large volume of sludge had been brought in and was ordered to be covered. However, it appears that municipal garbage, shredded refuse and bark have been disposed in this area instead. This material remains uncovered. Also those areas located by the old incinerator where large amounts of wood wastes were disposed also remains uncovered.

In regard to the screening, a large earthen berm has been placed along the north side of the site to provide screening. This berm is approximately 20 feet thick and 20 feet high. This berm is causing problems in the form of blowing dust. If at all possible, this berm should be stabilized to prevent erosion and dust blowing.

I have enclosed several photographs showing the present situation at the landfill site. Would you please forward this information onto the Attorney General's office per their request.

Gary F. Kulibert
Solid Waste Mgt. Coordinator


GFK:ct

Encl.


NOTED:


______________________ Date______________

00695










00694



Barn
Milled waste
Sludge
Misc. waste
#3
#4
7
8
Sludge
Bark
Milled
waste.
1
2
5
6
wood.
Metals
00693

#1

Lehner
7-14-75
gfk

E 503631JK

#3

Lehner
7-14-75
gfk

E 503631JK

#2

Lehner
7-14-75
gfk


00692

E 502421BC

#4

Lehner
7-14-75
gfk

E 503631JK



00691

Lehner
7-14-75
[illegible]

E 5 0 3 6 3 1 J K

#7

POLAROID ®

Lehner
7-14-75
[illegible]

E 5 0 2 4 2 1 B C

#5

00690

Lehner
7-14-75
[illegible]

E 5 0 2 4 2 1 B C

#6

#8

Lehner
7-14-75
[illegible]

E 5 0 3 6 3 1 J K